
## MEN'S GLOVES SIZING CHART

Circumference of hand	S 18-19cm 7-7.5"	M 20-21.5cm 8-8.5"	L 23-24cm 9-9.5"	XL 24-25.5cm+ 9.5-10"+
Length of hand	16.5-18cm 6.5-7"	19-20cm 7.5-8"	21.5-23cm 8.5-9"	23-24cm 9-9.5"



## HOW TO MEASURE

- Circumference of hand Measure around the fullest part of the hand around the knuckles and excluding the thumb.
- · Length of Hand Measure from the wrist to the top of your middle finger.