


PRODUCT IDENTIFICATION



Features of the L4 G21M Mount

STANDARD LIMITED WARRANTY

For full warranty terms, contact Wilcox Customer Service at 603-431-1331.

WARRANTY CLAIM AND SERVICE INFORMATION


Wilcox must be contacted in the United States at (603) 431-1331 to assign a **Return Merchandise Authorization (RMA) / Service Call Number (SC)** prior to return shipment.

After an RMA/SC number is provided, Wilcox will accept a package at the address below, clearly marked with the number assigned as follows:

Wilcox Industries Corp.
RMA # _____
25 Piscataqua Drive
Newington, NH 03801

The product must be securely packaged, accompanied by purchasing information, a letter including sender's name, address, daytime phone number, date of manufacture, lot number and a description of the problem or work to be performed.

ADJUSTMENT RANGES



Clean the Mount by flushing away dirt with fresh water and/or wiping down the assemblies with a clean, damp cloth. If used in a salt water environment, flushing with fresh water and drying after use is recommended. If used extensively in a salt water environment, lightly lubricate stainless steel parts as needed. Vertical and horizontal adjustment and release mechanisms that are not kept free from debris may bind and the assembly may not lock the mount into the up or down position. Lubricate lightly as needed.

CARE AND MAINTENANCE

"Our Customer's Life Depends on It"™

Manufactured by:
WILCOX®
Wilcox Industries, Corp.
25 Piscataqua Drive
Newington, NH 03801-7816
Phone: +1 888-8WILCOX
+1 603-431-1331
Fax: +1 603-431-1221



WWW.WILCOXIND.COM
For troubleshooting service questions
contact Wilcox between 8am and 5pm EST.

GENERAL SAFETY WARNINGS

WARNING
When performing operations that could cause entanglement, ensure that the break away feature is not obstructed in any way.

OPERATION AND MAINTENANCE
INSTRUCTIONS FOR THE
WILCOX®
L4 G21 Mount with Breakaway Base
for the AN/PVS-21 NVG
CAGE: 004F1

Mount Up!®



28300G21M
(Mount Only)



28300G21
Wilcox Three Hole
Shroud & Lanyard




26000G02
L4 Series NVG
Head Mount
& Lanyard Only




© 2009-2022 Wilcox Industries Corp. All rights reserved. Printed in USA. Wilcox's line of L4 NVG Mounting Systems is Patent Pending. Wilcox®, the Wilcox "X" Logo and "Mount Up!" are federally registered trademarks of Wilcox Industries Corp. "Our Customer's Life Depends on It!" is a trademark of Wilcox Industries Corp. All other trademarks and registered trademarks in this manual are the property of their respective companies. Specifications and other data are subject to change without notice. **EAR99: Export license not required.**

INSTALLATION

To Attach the Helmet Mount Interface (HMI) to the Helmet



To Attach the Wilcox Three-Hole HMI to the Helmet



To Attach the (Optional) Ratchet Strap to the Helmet:

(MICH/ACH/CVC DEPICTED)



To Detach the (Optional) Ratchet Strap from the Helmet:


(MICH/ACH/CVC DEPICTED)



To Attach the NVG Mount:

(HMI DEPICTED)

1. SLIDE THE MOUNT RELEASE LEVER TO THE LEFT USING THE RIGHT FOREFINGER TO UNLOCK THE MOUNT RELEASE.
2. INSERT THE TOP MOUNTING GUIDE.
3. ROTATE THE MOUNT DOWNWARD UNTIL IT SEATS.
4. SLIDE THE MOUNT RELEASE LEVER TO THE RIGHT USING THE RIGHT THUMB TO SECURE.
5. PRESS THE MOUNT FIRMLY AT THE BASE TO SEAT, ALLOWING THE MOUNT TO ACHIEVE ITS POSITION.




To Detach the NVG Mount:


1. SLIDE THE MOUNT RELEASE LEVER TO THE LEFT USING THE RIGHT FOREFINGER TO UNLOCK THE MOUNT RELEASE.
2. REMOVE THE MOUNT.

To Attach the Wilcox NVG Shoe to the AN/PVS-21 Goggle:

1. IF PERMANENT INSTALLATION IS DESIRED, APPLY A DROP OF LOCTITE 271 TO THE THREADS OF THE SCREWS, AND SET ASIDE.
2. ATTACH THE BOTTOM OF THE NVG INTERFACE SHOE TO THE TOP OF THE AN/PVS-21 INTERFACE, ALIGNING THE HOLES TO THE FRONT OR BACK SET OF SCREWS AS DESIRED.
3. WHILE HOLDING BOTH WILCOX COMPONENTS CENTERED ON THE SHOE, INSERT THE SCREWS AND THREAD HAND TIGHT WITH A SCREWDRIVER.



To Attach the AN/PVS-21 Goggle to the NVG Mount:



To Detach the AN/PVS-21 Goggle from the NVG Mount:

DEPRESS THE NVG RELEASE BUTTON OF THE NVG MOUNT AND PULL OUTWARD WHILE HOLDING THE GOGGLE WITH ONE HAND.

OPERATION

To Adjust the Tilt Angle of the Mount:

TILT CAPABILITY FOR THE G21/G21M IS PROVIDED BY THE AN/PVS-21 GOGGLE. TO TILT, ROTATE THE TILT ANGLE ADJUSTMENT KNOB ON THE GOGGLE CW OR CCW.


To Adjust the Vertical Height of the Mount:



To Enable or Disable the Breakaway Feature:



To Perform a Primary Flip:



To Perform a Secondary Flip (Lower Profile Storage):

